

Order no. CX12NAF13001C

Date of inspection: 2017-6-21

Order information	
Client:	
Contact person:	
Manufacturer name:	
Inspection place:	Sheng Zhou Shao Xing China
Contact person: (Manufacturer/supplier)	Miss Zhou
Supplier:	
Description of product:	Grid lamp

Item No.	Type	Safety Mark	Lot / Batch size	Total no. of carton box	No. of units per carton
	NG-D4-418W	CE	300	300	1

Inspected By: _____
(Name in Block Letter)

(Signature)

Approved By: _____
(Name in Block Letter)

(Signature)

.....

Packing & Marking						
Item No.	Out Carton Size L/W/H (cm)	Out Carton Weight GW/NW (KG)	Inner Box L/ W/H (cm)	Inner Box GW/NW (KG)	Product L/W/H (cm)	Product weight (KG)
NG-D4-418W	64×62×9	4.28/3.80	/	/	/	3.70
Notices	Marking see appendix					

A. CONCLUSION AND INSPECTORS OPINION: OK Not OK Pending

☒ ☐ ☐

The inspected samples have been found to be in conformance with the clients pre-shipment requirements (AQL=Acceptable Quality Level);


AQL: Critical Defective: **Not Allowed**, Major Defective: **1.5**, Minor Defective: **4.0**

Sampling Plan:

Item No.	Lot/batch size(pcs)	Sample size Level II	Sample size Level S4
NG-D4-418W	300	50	

B. INSPECTION RESULTS:

(1) AQL Result:

Item No.		Level II			Level S4		
		Accept/ Reject	Actual Findings	Result	Accept/ Reject	Actual Findings	Result
NG-D4-418W	Critical Defective	Not allowed	0	Pass			
	Major Defective	2/3	0	Pass			
	Minor Defective	5/6	4	Pass			
Actual Findings							
Level II						S4	
Minor: Dirt-----2pcs Scratch----2pcs							

(2) **Component Check:**

(3) **Rating Label:**

Please see appendix

Result:


Result: Pass

(4) **Remarks/Observation:**

1. Hi-pot Test: 1.75KV 5mA 3s [The result is ok](#)





2. Earth Test: 10A < 50mΩ, [The result is ok](#)



3. Function Test : 230V 50Hz , [The result is ok](#)







(5) Appendix



.....OnlogSystem.....



.....OnlogSystem.....



.....OnlogSystem.....



The end of report